










Fig. 1



















Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18

Fig. 19a

500

502

Claimset ID# 20000307135816000127
 Dealership Mashni Motor Company
 P & A Code 1
 Submitted By Dave G Park
 Reviewer Jeremy Willard
 Date 3/7/00 1:57 PM EST
 Status New
 RO Number 563214
 VIN 12WHT61L9X5650604
 Make
 Model
 Model Year
 KILOMETERS 15632

512

516

518

514

521

520

Digital Imaging

Camera Docked

Reserve Claimset

Send Claimset

Next

Reset

508

510

504

NEW

Repair Item 1

Claim Status Approved

ACES Code P17JW

Symptoms Code

Customer Waiting

Parts on Hand

Paint

Description

506

DP> Customer reports broken cup holder.
 Holder should be replaced Thanks! Dave.
 JW> YOUR APPROVED TO REPLACE CUP HOLDER.
 THANKS, JEREMY. 1456
 DP>

MPH

12:54

015632

3/8/2000 1:44am

Fig. 196

502

Claimset ID# 20000307135816000127
 Dealership Mashri Motor Company
 P & A Code 1
 Submitted By Dave Park
 Reviewer Jeremy Willard
 Date 3/7/00 1:57 PM EST
 Status New
 RO Number 563214
 VIN 1ZWHT61L9X5650604
 Make
 Model
 Model Year
 Kilometers 15632

516 **Digital Imaging**

518 [Send Claimset] [Working on claim] [Next] [Reset]

514 [Receive Claimset]

508


504

NEW

Repair line item 1
 Claim Status Approved
 ACES Code P17JW
 Symptom Code
 Customer Waiting ☒
 Parts on Hand ☐
 Paint ☐
 Description

510

1ZWHT61L9X5650604




3/8/2000 1:44am

506

DP> Customer reports broken cup holder.
 Holder should be replaced Thanks! Dave.
 JW> YOUR APPROVED TO REPLACE CUP HOLDER.
 THANKS, JEREMY 1436
 DP>

700






Fig. 20b




Fig. 21a




Fig. 21b




Fig. 22